



BEVERAGE-AIR

VICTORY

SERVICE BULLETIN

Bulletin Number: SB00100002
Date: 03/04/2019

SUBJECT: UNIVERSAL CONTROL KIT

ISSUES DISCUSSED: RETURN CALLS AFTER KIT INSTALLATION

CAUSE: IMPROPER INSTALLATION

PART NUMBERS:

REFRIGERATORS: 00C30-123D-01

FREEZERS: 00C30-123D-01

ACTIONS NEEDED: SERVICE TECHNICIANS MUST FOLLOW THE MANUAL INCLUDED WITH THE KIT EXACTLY. PAY SPECIAL ATTENTION TO WHAT CONTROL YOU ARE REPLACING AND FIND THE INSTRUCTIONS FOR THAT SPECIFIC CONTROL. ALSO NOTE WHETHER YOU HAVE A FREEZER OR REFRIGERATOR. THE OFFSETS TO THE TEMPERATURE SENSORS **MUST** BE CHANGED IN THE UNIVERSAL CONTROL PARAMETERS OR THE UNIT WILL NOT OPERATE PROPERLY. IF YOU HAVE QUESTIONS IN THE FIELD PLEASE CALL THE TECHNICAL SERVICE AT THE NUMBER LISTED BELOW. IF YOU HAVE A KIT BUT HAVE MISPLACED THE MANUAL THERE WILL BE A LINK TO DOWNLOAD THE PDF VERSION IN THIS BULLETIN.

TECHNICAL SERVICE: 1-800-684-1199

UNVIERSAL KIT MANUAL: [Danfoss Universal Controller](#)
